


LDWSE
4.8.1
2/21/14

Sanga, Ravi

From: Dyer, Miles [mdyer@JorgensenForge.com]
Sent: Friday, February 21, 2014 5:16 PM
To: Ernst, William D; Dee Gardner; Philip Spadaro; Sanga, Ravi; Amy Essig Desai; Bob Romagnoli
Subject: Sheet Pile Update
Attachments: Cofferdam Progress 2-21-2014.jpg

The north wall has been completed. Installation is progressing on the west wall (bank). Upon completion of the west wall, the south wall will be installed and finally the east wall (channel side). This allows the crane operator to observe the sheet wall pieces as they are being installed. There has been no obstructions encountered to date which were not easily overcome. At the current rate of work, the coffer dam is expected to be completed late Wednesday or early Thursday.

Miles Dyer
Director, Environmental Programs



Jorgensen Forge Corporation
8531 East Marginal Way South
Seattle, Washington 98108
Office Ph#: (206) 965-1352
Mobile: (740) 777-7808
Fax: (206) 357-1071
mdyer@jorgensenforge.com

***** ATTACHMENT NOT DELIVERED *****

This Email message contained an attachment named
image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

***** ATTACHMENT NOT DELIVERED *****

